

**Appendix 2**  
*Attachment to Executive Report*

**Fire Risk Assessment Category A\* Items**

**CCTV Control Room**

- Extend existing fire alarm as required, link to main alarm in Market Hall.

**Burnley Town Hall**

- Improve fire separation in Basement Area;
- Remove old timber disused staircases & increase fire resistance to ceiling;
- Make all service duct doors meet ½ hr protection & keep locked;
- Increase level of Emergency Lighting in basement

**Burnley Markets Hall**

- Renew / extend emergency lighting, especially in Open Market area;
- Extend Smoke Detection in Open Market area.

**Contact Centre**

- Upgrade service duct doors in stairwell to meet ½ hour resistance.

**Cemetery Offices**

- Several new fire doors required;
- Upgrade four doors to meet ½ hour resistance;
- Increase the level of Smoke Detection.

**Towneley Hall**

- Upgrade all the doors in staircases and corridors to meet ½ hour resistance.

**Towneley Craft Museum**

- Install Emergency Lighting system throughout.

**Towneley Natural History Museum**

- Install Emergency Lighting system;
- Install Smoke Detectors
- Two new fire doors & casings required.